



## Recommended Spare Parts List BIRNS Model 5220 Corona HPSV Lighting System

### SCOPE

This document provides the BIRNS recommendation for stocking of spare parts for one unit of the Model 5220 BIRNS Corona HPSV Lighting System.

### RECOMMENDED SPARE PARTS

Item	Number <sup>1</sup>	Qty.	Description	Stock <sup>2</sup>	Lead time <sup>3</sup>
01	17F-028	1	Cable Assembly, Ballast-to-Light	No	4-6
02	17F-048	1	Cable Assembly, Power-to-Ballast, 40'	No	4-6
03	32G-006	1	Ultra-low-Hg TCLP-compliant Lamp, 1000w HPSV	Yes	3-4
04	35B-030	1	Dome, Corona, Quartz	No	6-8
05	52G-007	1	Silicone Spray, Can	Yes	2-3
06	56D-014	1	Support Ring, Dome Cushion	Yes	3-4
07	59A-151	2	O-ring, Dome Sealing	Yes	3-4
08	59A-152	2	O-ring, Rear Nut Radial Sealing	Yes	3-4
09	59A-153	2	O-ring, Retaining Ring	Yes	3-4
10	59A-154	2	O-ring, Rear Nut Face Sealing	Yes	3-4
11	59A-175	6	O-ring, Receptacle Connector Face	Yes	2-3
12	59A-176	6	O-ring, Receptacle Connector Radial	Yes	2-3
13	70A-035	1	Tool, Retaining Ring Removal	No	4-6

<sup>1</sup>This is the BIRNS part number for the item. The number consistently cross-references on all BIRNS documents, including drawings, Manuals, and Bills of Material.

<sup>2</sup>This specifies whether or not BIRNS keeps the item in BIRNS warehouse stock.

<sup>3</sup>The average lead for the item, in weeks, if not in BIRNS warehouse stock.